




TS100
Presentation
Scanner (2D)


Horizontal Installation

Install the angle stand upward Place scanner horizontally




Pitch Forward Installation

Install the angle stand upward Pitch forward 15°



Connecting The Scanner

Connect USB cable to a free USB port of a host computer. The TS100 is now ready to use.



Test & Finish

Open a word processing program such as Microsoft Word or Notepad and scan the following barcode:



If the word "Unitech" appears on the screen, you have successfully installed your scanner.

LED Description

- A green light then a blue light: Switch on
- Blue light always on: Scanner Ready
- Green light flash once: Configuration commands good read
- Red light flash once: Configuration commands error
- Green light flash once: Barcode good read

Buzzer Description

- One long beep: Switch on
- One long and low beep: Configuration commands Error
- One short and low beep: Configuration commands good read
- One short and high beep: Barcode Good Read

Default Setting



Factory Default



Middle

Beeper Control



Low



High*

Note: The code with (*) is the factory default.

Operation Mode



Printed-Reading Mode*



Screen-Reading Mode

We suggest using Screen-Reading Mode when scanning barcodes on the screen. (Default is Printed-Reading Mode)

Good Read Indicator



On*



Off

Display Version



Software Version

Data Terminator



CR*



LF



TAB



CR/LF

Language Settings



USA*



UK



France



Turkey-F



Germany



Italy



Spain



Japan



Brazil



Portugal



Belgium



<http://www.ute.com/>